

# HYTORC

## TOOL MODEL: VERSA 3X PRESSURE/TORQUE CONVERSION CHART

### Standard Torque Chart

PRESSURE IN PSI	TORQUE IN			PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	437	60	592	104
1600	468	65	635	110
1800	530	73	719	124
2000	593	82	803	138
2200	654	90	886	152
2400	715	99	970	165
2600	776	107	1053	179
2800	838	116	1136	193
3000	899	124	1219	207
3200	962	133	1304	220
3400	1024	142	1389	234
3600	1087	150	1474	248
3800	1150	159	1559	262
4000	1213	168	1644	276
4200	1275	176	1729	290
4400	1338	185	1814	303
4600	1401	194	1900	317
4800	1464	203	1985	331
5000	1527	211	2070	345
5200	1590	220	2156	358
5400	1653	229	2241	372
5600	1716	237	2327	386
5800	1780	246	2412	400
6000	1843	255	2498	414
6200	1906	264	2584	427
6400	1969	272	2670	441
6600	2033	281	2756	455
6800	2096	290	2842	468
7000	2160	299	2928	482
7200	2223	307	3014	496
7400	2287	316	3100	510
7600	2350	325	3186	524
7800	2414	334	3272	538
8000	2477	343	3358	552
8200	2540	351	3443	565
8400	2602	360	3528	579
8600	2665	369	3613	593
8800	2728	377	3698	607
9000	2791	386	3783	620
9200	2853	395	3867	634
9400	2915	403	3951	648
9600	2976	412	4035	662
9800	3038	420	4119	676
10000	3100	429	4203	690