

# HYTORC

## TOOL MODEL: VERSA 2X PRESSURE/TORQUE CONVERSION CHART

### Standard Torque Chart

PRESSURE IN PSI	TORQUE IN			PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	204	28	277	104
1600	220	30	298	110
1800	251	35	340	124
2000	282	39	382	138
2200	311	43	421	152
2400	339	47	460	165
2600	368	51	499	179
2800	396	55	537	193
3000	425	59	576	207
3200	455	63	617	220
3400	486	67	659	234
3600	516	71	700	248
3800	547	76	741	262
4000	577	80	782	276
4200	607	84	822	290
4400	636	88	862	303
4600	665	92	902	317
4800	695	96	942	331
5000	724	100	982	345
5200	756	105	1024	358
5400	787	109	1067	372
5600	818	113	1109	386
5800	849	117	1151	400
6000	880	122	1194	414
6200	910	126	1234	427
6400	940	130	1275	441
6600	970	134	1315	455
6800	1000	138	1356	468
7000	1030	142	1396	482
7200	1061	147	1438	496
7400	1092	151	1480	510
7600	1123	155	1523	524
7800	1154	160	1565	538
8000	1185	164	1607	552
8200	1216	168	1649	565
8400	1247	172	1690	579
8600	1278	177	1732	593
8800	1309	181	1774	607
9000	1339	185	1816	620
9200	1370	190	1858	634
9400	1401	194	1900	648
9600	1432	198	1942	662
9800	1464	202	1984	676
10000	1495	207	2026	690